Feasibility of Decentralised Deployment of Xpert MTB/ RIF Test at Lower Level of Health System in India

Neeraj Raizada¹*, K. S. Sachdeva², Achuthan Sreenivas³, Bhavin Vadera¹, R. S. Gupta², Malik Parmar³, Shubhangi Kulsange¹, Ameet Babre¹, Rahul Thakur¹, Christen Gray⁴, Ranjani Ramachandran³, Umesh Alavadi¹, Mayank Ghedia³, Balasangameshwara Vollepore¹, Puneet Dewan³, Catharina Boehme⁴, C. N. Paramsiyan¹

1 Foundation for Innovative New Diagnostics, New Delhi, India, 2 Central TB Division, Government of India, New Delhi, India, 3 World Health Organization, India Country Office, New Delhi, India, 4 Foundation for Innovative New Diagnostics, Geneva, Switzerland

Abstract

Background: Xpert MTB/RIF is an automated cartridge-based nucleic acid amplification test that has demonstrated its potential to detect tuberculosis and rifampicin resistance with high accuracy. To assist scale-up decisions in India, a feasibility assessment of Xpert MTB/RIF implementation was conducted within microscopy centres of 18 RNTCP TB units.

Methods: As part of programme-based demonstration of Xpert MTB/RIF implementation, we recorded and analysed association between key implementation factors and the ability of test to produce valid results. Factors contributing to test failures were analysed from GeneXpert software data which provides 'failure codes' and causes for test failures.

Results: From March'12 to January'13, total 40,035 suspects were tested by Xpert MTB/RIF, and 39,680 (99.1%) received valid results (Cumulative: 37157 (92.8%) on first attempt, 39410 (98.4%) on second attempt, 39637 (99.0%) on third attempt and 39680 (99.1%) on more attempts). Overall initial test failure was 2,878 (7.2% (4%–17%)); of these, 2,594 (90.1%) were retested and produced valid results. Most frequent reason of test failure was inadequate sample processing or equipment malfunction (3.9%). Other reasons included power failure (1.1%), cartridge integrity/component failure (0.8%), device-computer communication error (0.5%), and temperature-related errors (0.08%). Significant variation was observed in failure rate in two cartridges lots.

Conclusion: Installation required minimal infrastructure modifications and concerns about adequacy of human resources under public sector facilities and temperature extremes proved unfounded. Under routine conditions, Xpert MTB/RIF provided 99.1% valid results in TB suspects with low overall failure rates (7.2% initial failure, 0.9% final failure); devices provided valuable real-time feedback on reasons for test failure, which were used for rapid corrective action. High modular replacement (32%) and inter-lot cartridge performance variation remain sources of concern, and warrant close monitoring of failure rates as a key quality indicator.

Citation: Raizada N, Sachdeva KS, Sreenivas A, Vadera B, Gupta RS, et al. (2014) Feasibility of Decentralised Deployment of Xpert MTB/RIF Test at Lower Level of Health System in India. PLoS ONE 9(2): e89301. doi:10.1371/journal.pone.0089301

Editor: Vishnu Chaturvedi, California Department of Public Health, United States of America

Received September 16, 2013; Accepted January 17, 2014; Published February 26, 2014

Copyright: © 2014 Raizada et al. This is an open-access article distributed under the terms of the Creative Commons Attribution License, which permits unrestricted use, distribution, and reproduction in any medium, provided the original author and source are credited.

Funding: The study was funded by United States Agency for International Development (USAID) through World Health Organization (WHO). FIND was responsible for study design, implementation, training, study coordination and monitoring, data analysis, and writing of the report in close coordination with WHO and Central TB Division. The funder had no participation in the design, implementation, analysis, or preparation of any reports or manuscript. The funders had no role in study design, data collection and analysis, decision to publish, or preparation of the manuscript.

Competing Interests: I have read the journal's policy and have the following conflicts: NR, BV, SK, AB, RT, CG, UA, BV, CB and CNP are am employed by FIND, a non-profit organization that collaborates with industry partners, including Cepheid Inc., for the development and evaluation of new diagnostic tests. However, this doesnot alter our adherence to all the PLOS ONE policies on sharing data and materials. Further, none of the authors have any financial or market interest in the product being evaluated under the study.

* E-mail: drneerajraizada@gmail.com

Introduction

Earlier and improved detection of all types of TB are global priorities for TB control. As conventional laboratory methods are time consuming, newer technologies for rapid detection remain as the focus of TB research and development. [1]

The WHO endorsed Xpert MTB/RIF (Cepheid, Sunnyvale, CA, USA) is a cartridge-based fully automated nucleic acid amplification test (NAAT) for TB case detection and rifampicin resistance detection, suitable for use in disease-endemic countries [2]. It extracts DNA, concentrates, amplifies, identifies targeted nucleic acid sequences in the TB genome, and provides results from unprocessed sputum samples in less than 2 hours with minimal hands-on technician time. [2]

The Xpert MTB/RIF test in principle enables diagnosis of TB and rifampicin-resistant TB at the clinics equipped with basic laboratory infrastructure supported by personnel with minimum technical skills. [3] Although testing with Xpert MTB/RIF does In controlled studies the Xpert MTB/RIF assay has demonstrated its potentials to detect tuberculosis and rifampicin-resistant TB with high sensitivity and specificity. [5] However, diagnostic tests performing well in controlled settings may not always perform optimally in settings of intended use. [6] Delivery systems have to account for several factors including specimen collection and transportation efficiency, device up-time, test reliability, environmental extremes, human resource constraints, reporting of results, supply chain, and multiple other critical factors beyond test accuracy. Therefore, before investing in scale-up, operational assessment of implementation should be conducted at the level of intended use. Accordingly, WHO has recommended countryspecific operational research. [4]

In the present demonstration, we assessed operational feasibility of introducing Xpert MTB/RIF within the existing microscopy centers functioning under Revised National TB Control Programme (RNTCP) of India to inform decisions on scale-up of the technology under the programme. The objectives of the study were to collect evidence on the feasibility of implementation of Xpert MTB/RIF under routine conditions in existing microcopy centers; to assess test failure rates and the impact of key implementation factors on the assay in decentralized settings including the effect of variable temperature conditions, power failure, etc.; and to identify key issues that need to be monitored while implementing Xpert MTB/RIF test.

Methods

Study setting: The present demonstration was conducted in 18 selected RNTCP TB programme management units (TU) with an aggregate population of 8.8 million. Each TU caters on average to a population of 0.5 million, and encompasses 4-6 Designated Microscopy Centers (DMCs), and each DMC covers 2-4 health centres. Anyone attending these health facilities and suspected to have pulmonary TB are referred to a DMC for sputum smear microscopy. The 18 Xpert MTB/RIF study sites were selected by RNTCP to encompass the range of diverse geographic and demographic settings across the country, but restricted to those able to provide free MDR TB treatment services to those diagnosed for ethical purposes. 8 sites were in rural area, 6 sites were in urban area and 4 sites were in tribal and hilly areas covering a population of 3.9 million, 3.4 million and 1.4 million, respectively (Figure 1), and covering 99 DMCs and their linked health facilities.

Either one or two GeneXpert instruments equipped with 4 modules (GX-IV R2) were installed at all study sites. They were placed at the existing DMCs co-located within a selected TU by identifying a small room with electricity outlets, securing the space, adding air conditioner, and installing uninterrupted power supply units (UPS). Additionally, a cold room was required for cartridge storage. As ambient temperature beyond 30°C may affect assay performance, WHO guidance on rapid implementation of the Xpert MTB/RIF diagnostic test recommends temperature control. [4] A temperature gauge is preinstalled inside the GeneXpert instrument; when internal equipment temperature rises above the permissible limit, the equipment will not initiate an assay or will generate an 'error' result if there are assays underway. The UPS units were required to provide a minimum of 2 hours of power back-up, the maximum time for a single assay to complete. At two sites which were experiencing regular power failures, extended solar power back-up was provided during the study for the GeneXpert instruments.

Special arrangements were made for transportation of sputum samples from microscopy centres and public health facilities to the respective GeneXpert lab. Distance and travel time was assessed and a site-specific transportation mechanism was tailored to ensure that sputum samples reached the GeneXpert lab on the same day of collection even from more remote health facilities.

A standardised algorithm (Figure 2) approved by the national technical committee for the project was used for the diagnosis of TB patients. All staffs were trained for uniform implementation of the algorithm across all sites; additionally, all were given hands-on training on the GeneXpert testing procedure as per manufacturer recommendations.

Feasibility assessment: The feasibility of Xpert MTB/RIF implementation was primarily assessed in terms of the ability of the assay to return a valid patient result. The absence of a valid test result for any given assay initiated was defined as a 'test failure' regardless of the underlying reason. Per patient, a test failure based on a single Xpert MTB/RIF test was defined as 'initial test failure'; those initial test failures that could not be resolved on repeat assay, or which could not be re-tested for operational reasons, were defined as 'final test failure'. We analysed the frequency of various reasons for the occurrence of test failure. In parallel, we routinely collected information on factors that may have affected failure rates, such as installation and training errors, operational nonavailability, ambient temperature, power failure, equipment reliability, and cartridge manufacture lot.

The manufacturer has classified possible test failure causes as 'error', 'invalid' or 'no result'. [7] An 'error' result indicates that the Xpert MTB/RIF assay in a given test was aborted by internal quality control mechanisms including improper filling of the cartridge reaction tube, cartridge reagent probe integrity failure, cartridge internal pressure excess, or equipment malfunction. All 'error' results are accompanied by specific error codes that provide additional information as to the underlying cause of failure. An 'invalid' result indicates that the polymerase chain reaction (PCR) has failed, usually due to the presence of PCR inhibitors. A 'no result' outcome indicates that the test underway was prematurely terminated either by external or internal factors during cartridge loading process, such as power failure, manual termination of the test by the operator, or one of the equipment or cartridge component failures. [7]

Under the study, for a patient, in case of 'error' or 'no result' outcome, repeat testing was performed on the same sample; for an "invalid" result, repeat testing was performed on a second fresh sputum sample due to concern over PCR inhibitors in the original specimen. The initial and final test failure rates were assessed across the study sites by directly extracting raw data from every test run initiated and recorded by the GeneXpert software.

Across 18 study sites, there were 27 GX–IV R2 instruments with 4 modules each for a total of 108 modules. Each module installed in a GeneXpert instrument functions independently from one another. A module failure leads to replacement of the specific module by the manufacturer if the equipment is under warranty or is covered under a maintenance contract. The frequency of such failures was assessed. At the time of analysis, error rates of prior 3 months were calculated. Modules with an error rate above 75th percentile of error rate of all functional modules were defined as sub-optimally performing. Further analysis was conducted to assess trends in the performance of these modules over a period of time.

Similarly, to identify any possible variation between the performances of different lots of Xpert MTB/RIF cartridges, a lot-wise analysis of the invalid rate was undertaken as invalid results are generally considered to be independent of manual



Figure 1. Site Locations: Geographical locations of the 18 project sites across India. doi:10.1371/journal.pone.0089301.g001



Figure 2. Diagnostic Algorithm.

doi:10.1371/journal.pone.0089301.g002

errors or other external factors affecting the overall test performance.

Ethics statement: The study protocol was approved by the Institution Ethics Committee of the National Tuberculosis Institute, Bangalore, India. Structured informed consent forms were used for obtaining written consent from all suspects enrolled in the study. Before taking consent, patients were informed about the study in vernacular language by the trained staff. For illiterate patients, after explaining in their mother tongue, the consent was taken in presence of literate witness. Approval for the study was granted by the Central TB Division, Ministry of Health and Family Welfare, Government of India.

Results

Installation and training: The implementation of Xpert MTB/ RIF testing began in 2012 at 3 demonstration sites in March 2012, scaled up quickly to 13 sites in May, and initiated at all 18 sites by August 2012. Xpert MTB/RIF assays were performed by the existing public sector laboratory technicians having no prior experience in molecular testing after a one-day structured handson training. Within 6 months of initiation an average enrolment of more than 5000 suspects per month was achieved across the project. The median number of tests conducted per working day per machine was 8, (IQR 5-12). No formal training sessions were required over the course of the project, though in instances where error codes more frequently indicated inappropriate sample processing, one-on-one re-sensitization on procedures were conducted.

Test failure rate: By the end of January 2013, a total of 42,971 Xpert MTB/RIF tests were conducted on 40,035 individual TB suspects (Table 1). A valid result was obtained for 37,157 (92.8%) on the first attempt. Out of the 2,878 initial test failures, repeat tests were done on 2,594 (90.1%), among which results were available from 2,523 (97.3%). Of the 2,594 TB suspects subjected to repeat testing, 2,253 specimen had valid results after a single repeat test and another 227 after a second repeat test (Table 2). Altogether, 39,680 (99.1%) of all TB suspects were provided valid results after repeat testing (Table 1, Table 2).

The initial test failure rate was 7.2%, with a range of 3.9% to 14.2% across all 18 sites (Table 1, Table 2). Initial test failures were mostly classified as 'errors' [1,790 (4.5%)], with fewer 'no results' [629 (1.6%)] or 'invalid' results [459 (1.1%)] (Table 1).

Most of the repeat tests were also conducted on the same specimen and on the same day, without inconvenience to patients. Of the 2,594 TB suspects subjected to repeat testing, 1,998 repeat testing were performed on the same specimen. 1,961 (98.1%) of these were resolved. The other 596 were tested on a different

specimen of which 562 (94.3%) were resolved with a valid test result.

Test failure cause analysis: As per the test failure codes generated by the Xpert MTB/RIF, leading cause of test failure was sample processing error and equipment malfunction, contributing to a total of 1660 of 3291 test failures. The frequency of various factors contributing to test failures is described in Figure 3 and Table 3. Of these 1660 failures, more than 75% (1260) occurred at 9 sites. Similarly, more than 80% of the 515 invalid test results occurred across 9 sites (Table 2).

452 (1.1%) assays generated errors due to power supply related issues. 5 sites accounted for a bulk of such errors, 328 (72%). At two of these sites, as an intervention, solar power backup was provided which brought down the power-outage related error rate from 2.1% (131/6381) to 0.9% (18/2064) (p = <0.001, Pearson's Chi-Square Test).

A total of 35 (0.08%) test failures were associated with temperature related issues. These test failures were reported from 11 out of 18 project sites and 77.1% (27) of the 35 temperature related test failures occurred at 6 sites. These test failures were compared with the maximum and minimum ambient temperature recorded in the lab on the particular day when test failures occurred. This comparison showed that majority of these failures, i.e. 30 (85.7%), were caused by inadequate exhaust of warm air from the equipment and only 5 (14.3%) could be attributed to high ambient temperature.

Other causes for test failures were individual cartridge-related failures such as internal cartridge integrity test failure, cartridge syringe stall, cartridge component failure, etc. (325, 0.8%). Finally, loss of communication between modules and computer system accounted for 202 (0.5%) errors; however, 81.7% of these communication errors occurred at only 4 sites. (Figure 3, Table 3).

No trends on the basis of regional distribution, demographic profile or level of decentralisation of these sites were found in the factors contributing to the occurrence of test failures (Table 3).

Cartridge lot and module analysis: Stratification of test results by manufacturing lots showed that two particular cartridge lots were associated with a much higher frequency of test failures, due mostly to 'invalid' results. Of the 19 cartridge lots used 17 had median invalid rates of 0.5% (range 0.0 to 0.7%) whereas two lots had significantly higher invalid rates of 2.9% (14/487) and 5.3% (364/6869). Because cartridge-related test failures were immediately signalled to the device operators, most patients tested by this particular cartridge lot were re-tested and provided test results.

Of the total 108 modules in the study, 34 required replacements on account of various performance related issues; 10 had an overt malfunction and 24 showed degraded performance in test validity rates indicating impending malfunction. Of the 10 replaced modules, 7 modules had less than three months of data and were

Table 1. Initial test results and final test results on Xpert MTB/RIF (N = 40,035 patients tested).

| | No. of initial tost | | | | | |
|--------------|---------------------|-------|--------------------|---------------------------|-------|--------------------|
| Test Results | results | % | Range across sites | No. of final test results | % | Range across sites |
| Valid | 37157 | 92.8% | 85.8% - 96.1% | 39680 | 99.1% | 96.5% - 100% |
| Failure * | 2878 | 7.2% | 3.9% - 14.2% | 355 | 0.9% | 0.04% - 3.5% |
| Error | 1790 | 4.5% | 2.6% - 11.2% | 177 | 0.4% | 0% - 2.7% |
| Invalid | 459 | 1.1% | 0.2% - 2.6% | 142 | 0.4% | 0% -1.5% |
| No Result | 629 | 1.6% | 0% - 3.9% | 36 | 0.1% | 0% -0.5% |

* Break up of test failure results - Error, Invalid, No results

doi:10.1371/journal.pone.0089301.t001

| Number of tests per patient | Number of patient specimen tested | Patients with valid result | % | Test failures | Test failures retested | % | Test failures not repeated | % | Cumulative number of valid results | % |
|--------------------------------|---|----------------------------------|-------|---------------|------------------------------|-------|-------------------------------|-------|--|-------|
| Single test | 40035 | 37157 | 92.8% | 2878 | 2594 | 90.1% | 284 | 9.9% | 37157 | 92.8% |
| Single repeat test | 2594 | 2253 | 86.9% | 341 | 287 | 84.2% | 54 | 15.8% | 39410 | 98.4% |
| Repeat tests twice | 287 | 227 | 79.1% | 60 | 44 | 73.3% | 16 | 26.7% | 39637 | %0.66 |
| 3 or more repeat tests | 60 | 43 | 71.7% | 17 | 16 | 94.1% | - | 5.9% | 39680 | 99.1% |
| doi:10.1371/journal.pone.008 | 39301.t002 | | | | | | | | | |

Table 2. Number of tests conducted per patient on Xpert MTB/RIF far a valid result (N = 40,035 patients tested).

1 1

1

Xpert MTB/RIF: Feasibility Assessment

excluded from analysis due to a low comparative number of tests done (average 68 tests per module). 24 modules were identified with sub-optimal performance on account of higher test error rate as compared to the other modules. The overall test error rate in these 24 modules was 6.1%, while the overall test error rate in rest of 73 modules was 3.3% (p<0.001). It was observed that performance of these 24 modules had deteriorated over a period of time since installation (Figure 4). These 24 modules were later replaced by the manufacturer.

Discussion

This multi-centre demonstration has shown the striking feasibility and ease of Xpert MTB/RIF implementation across a diverse range of settings, utilizing the existing human resources and infrastructure found in public sector microscopy centres. Realtime feedback on reasons for test errors directly from the devices allowed for easy and rapid detection of implementation gaps and led to quick correction of most causes. Concerns about the adequacy of public sector human resources, facilities, and temperature extremes proved unfounded. Staff required minimal training, and the low frequency of sample processing errors attested to the effectiveness of this minimalistic approach to implementation. Installation required only minor infrastructure modifications and provision of power backup, and areas with particularly poor power supply were well-served by low-cost solar power battery recharging, as demonstrated by the low frequency of test interruptions. With the routine addition of room air conditioners, temperature-related errors were quite rare.

Implementation of Xpert MTB/RIF resulted in a very high percentage (99.1%) of suspects being provided with valid results. Other studies conducted on Xpert MTB/RIF assay elsewhere have also documented similar high proportion of interpretable results. [5–6] [8] A very large implementation programme of Xpert MTB/RIF by the National TB Programme of South Africa has reported 97.3% interpretable results on a large sample size. [9] These findings highlight the usefulness of monitoring initial and final test failure outcomes and repeat testing of all initial test failures in ensuring a high proportion of valid results.

The proportion of interpretable results after retesting on Xpert MTB/RIF was significantly higher than other diagnostic tools recommended by WHO for detection of rifampicin resistant TB cases. A key factor contributing and crucial to the high proportion of interpretable results under the study was the feasibility of rapid retesting and thereby resolving a significant proportion of test failures on the same specimen, in absence of which proportion of interpretable results would have been significantly less. Studies conducted with MTBDR plus line probe assays for the diagnosis of DR-TB reported 92%-97% interpretable results. [10-14] Although liquid culture and DST systems for diagnosis provide a higher sensitivity and specificity, they are known to be more prone to contamination. Even in experienced laboratories, approximately 5-10% of specimens cannot yield results because of contamination. [15-16] Similarly, for the laboratory diagnosis of sputum smear negative TB, Xpert MTB/RIF with the advantages of a quick turn-around time, yield of a high proportion of reportable results and feasibility of rapid roll-out, provides a very promising alternative to solid and liquid culture testing for the diagnosis. [17]

The leading cause of test failure results observed in the present study was due to inadequate sample processing and equipment malfunction. Similar findings were documented by the early implementers of Xpert MTB/RIF assay. [18–19] Majority of the test failures on account of inadequate sputum processing were attributed to high viscosity of a small proportion of sputum



Figure 3. Reasons for test failure. doi:10.1371/journal.pone.0089301.g003

samples. This finding suggests that to decrease such test failures, the incubation period of sputum in the sample processing buffer may be allowed for an additional 10 minutes for specimen with high viscosity [20].

Like any other automated laboratory technology, Xpert MTB/ RIF requires a stable electric power supply, and even short term interruption of power would result in test failures. [4] In the present study, 1.1% initial test failures were attributed to power failure as some of the sites had prolonged power outage. The feasibility of effectively addressing power related issues with interventions such UPSs and solar power back up was demonstrated adequately in the present study.

The manufacturer recommends a maximum of 30°C ambient operating temperature for the operation of GeneXpert instrument and data on the robustness of the device under prolonged periods of temperature exceeding 30°C are not available. [17] Our experience with over 10 months at sites situated at predominantly warm settings, established that the temperature related concerns in Xpert MTB/RIF testing could be very effectively addressed with the installation of air conditioning units. Even during frequent power failures at the study sites leading to absence of airconditioning, the temperature was usually maintained within the desired range and overall temperature related errors in our study were rare. It was further observed that majority of temperature associated errors was related to inadequate exhaust of warm air from the equipment either due to clogging of exhaust fan filter due to dust or inappropriate positioning of equipment. Based on our observation we recommend regular cleaning of fan filter along with appropriate positioning of the instrument to allow free flow of air to minimize the frequency of temperature related errors.

In the study, significant variation in the performance of GeneXpert modules and Xpert MTB/RIF cartridges was observed. Cartridges from two lots identified as associated with high failure rates were returned to the manufacturer for further investigation. However, it needs to be noted that this observation in one of the two lots was based on very small sample of tests and may need to be validated on a larger sample. The most striking finding, however, was that this could be rapidly detected – indeed this failure code analysis provides robust rapid data for ongoing automated quality assurance. The implementation of networked, real-time central monitoring software is expected to further aide

early detection of potentially problematic lots or modules, if and when such problems arise.

While the performance of some modules deteriorated with time irrespective of the workload, performance of other modules continued to be satisfactory during the study period. Early implementation of GeneXpert technology in programmatic settings in Democratic Republic of Congo reported 39% module replacements due to technical reasons including unexplained high error rates in less than one year of use. [21] These findings warrant regular monitoring of inter-modular and inter-lot variation in performance of the Xpert MTB/RIF assay and any deviation in the performance need to be reported immediately to the manufacturer.

Overall it was observed that GeneXpert has the prerequisite robustness for rapid scale up at decentralised settings while maintaining quality of results. We were able to effectively address concerns related to ambient temperatures in warm climatic settings and erratic power supply. Further the study identified some aspects related to Xpert MTB/RIF testing such as initial and final test failure rate, inter-modular variation in performance over time, inter-lot variation in performance, etc. that may need to be monitored nationally, while rolling out this technology and deploying large number of systems.

Replacement of dysfunctional modules was possible as all the equipments were either under warranty or annual maintenance contract with the manufacturer, highlighting the importance of having such systems/services in place.

Conclusion

This multi-centre demonstration has shown striking feasibility and ease of Xpert MTB/RIF implementation across a diverse range of settings, utilizing the existing human resources and infrastructure found in public sector microscopy centres. Installation required only minimal infrastructure modifications of airconditioning and power back-up plus low-cost solar power battery charges in areas with particularly poor power supply. Concerns about the adequacy of public sector human resources, facilities, and temperature extremes proved unfounded.

Under routine conditions in public sector RNTCP microscopy centres, Xpert MTB/RIF routine testing of patients suspected of Table 3. Site wise distribution of various factors contributing the Xpert MTB/Rif test failures.

| Site | Site A | Site B | Site C | Site D | Site E | Site F | Site G | Site H | Site I | Site J | Site K | Site L | Site M | Site N | Site O | Site P | SiteQ | Site R | TOTAL |
|---|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|---------------|--------------|--------------|--------------|--------------|----------------|
| Site profile | Rural | Urban | Urban | Urban | Urban | Rural | Rural | Urban | Tribal | Rural | Tribal | Urban | Urban | Rural | Hilly | Rural | Tribal | Rural | |
| Grand Total | 5303 | 4741 | 4256 | 3737 | 3300 | 3177 | 3142 | 2917 | 2505 | 2049 | 1453 | 1361 | 1218 | 1150 | 801 | 751 | 679 | 431 | 42971 (92%) |
| Valid | 4744 (89%) | 4495 (95%) | 4027 (95%) | 3468 (93%) | 3081 (93%) | 2997 (94%) | 2883 (92%) | 2612 (90%) | 2320 (93%) | 1966 (96%) | 1367 (94%) | 1134 (83%) | 1101 (90%) | 1060 (92%) | 691 (86%) | 716 (95%) | 614 (90%) | 404 (94%) | 39680 (4%) |
| Sample processing & Equipment related issues | 217 (4%) | 105 (2%) | 151 (4%) | 131 (4%) | 98 (3%) | 72 (2%) | 118 (4%) | 176 (6%) | 71 (3%) | 38 (2%) | 69 (5%) | 188 (14%) | 76 (6%) | 46 (4%) | 51 (6%) | 16 (2%) | 25 (4%) | 12 (3%) | 1660 (1%) |
| Invalid | 107 (2%) | 13 (0%) | 26 (1%) | 17 (0%) | 47 (3%) | 59 (2%) | 79 (3%) | 26 (1%) | 6 (0%) | 6 (0%) | 8 (1%) | 31 (2%) | 19 (2%) | 23 (2%) | 29 (4%) | 13 (2%) | 2 (0%) | 4 (1%) | 515 (1%) |
| Power failure | 113 (2%) | 28 (1%) | 4 (0%) | 60 (2%) | 7 (0%) | 24 (1%) | 36 (1%) | 44 (2%) | 70 (3%) | (%0) 0 | 9 (1%) | 4 (0%) | 8 (1%) | 9 (1%) | 20 (2%) | (%0) 0 | 12 (2%) | 4 (1%) | 452 (1%) |
| Cartridge related issue | 34 (1%) | 82 (2%) | 42 (1%) | 10 (0%) | 31 (1%) | 10 (0%) | 8 (0%) | 42 (1%) | 19 (1%) | 13 (1%) | (%0) 0 | (%0) 0 | 6 (0%) | 6 (1%) | 6 (1%) | 2 (0%) | 10 (1%) | 4 (1%) | 325 (0%) |
| Module communi- cation loss | 73 (1%) | 10 (0%) | 2 (0%) | 39 (1%) | 33 (1%) | 4 (0%) | (%0) 6 | 7 (0%) | (%0) 0 | 20 (1%) | (%0) 0 | (%0) 0 | (%0) 0 | (%0) 0 | (%0) 0 | (%0) 0 | 3 (0%) | 2 (0%) | 202 (0%) |
| Other | 8 (0%) | 6 (0%) | 4 (0%) | 2 (0%) | 1 (0%) | 5 (0%) | 2 (0%) | 3 (0%) | 4 (0%) | 5 (0%) | (%0) 0 | 4 (0%) | 7 (1%) | 4 (0%) | 3 (0%) | (%0) 0 | 3 (0%) | 1 (0%) | 62 (0%) |
| Multiple | (%0) 0 | 1 (1%) | (%0) 0 | 7 (0%) | 0 (0%) | 3 (0%) | 8 (0%) | (%0) 0 | 12 (0%) | (%0) 0 | 0 (0%) | (%0) 0 | (%0) 0 | 1 (0%) | 1 (0%) | (%0) 0 | 7 (1%) | (%0) 0 | 40 (0%) |
| Temperature related | 2 (0%) | 1 (1%) | (%0) 0 | 6 (0%) | 2 (0%) | 3 (0%) | 0 (%0) 0 | 7 (0%) | 4 (0%) | 1 (0%) | 0 (0%) | 0 (%0) 0 | 1 (0%) | 1 (0%) | (%0) 0 | 4 (0%) | 3 (0%) | (%0) 0 | 35 (0%) |
| Total test failure | 554 (10%) | 246 (5%) | 229 (5%) | 272 (7%) | 219 (7%) | 180 (6%) | 260 (8%) | 305 (10%) | 186 (7%) | 83 (4%) | 86 (6%) | 227 (17%) | 117 (10%) | 90 (8%) | 110 (14%) | 35 (5%) | 65 (10%) | 27 (6%) | 3291 (8%) |
| doi:10.1371/jou | urnal.pon | e.0089301 | 1.t003 | | | | | | | | | | | | | | | | |



Figure 4. Trend in error rates of modules. doi:10.1371/journal.pone.0089301.g004

TB provided valid results in 99.1% of TB suspects tested with an overall low failure rates (7.2% initial failure rate (4–17%), 0.9% final failure rate).Devices provided valuable real-time feedback on reasons for test failure, which were used for rapid corrective action. Module reliability (32% required replacement) and interlot variation of cartridges remain sources of concern, and warrant close central monitoring of failure rates as an indicator of potential quality problems. Further, in depth analysis of cost effectiveness of

References

- World Health Organization The Stop TB Department (2010) Roadmap for rolling out Xpert MTB/RIF for rapid diagnosis of TB and MDR-TB.
- World Health Organization (2010) Frequently Asked Questions on Xpert MTB/RIF assay: 1–5.
- Evans CA (2011) GeneXpert A Game-Changer for Tuberculosis Control? PLoS Med 8: 8–11. doi:10.1371/journal.pmed.1001061. Available: http:// www.ncbi.nlm.nih.gov/pmc/articles/PMC3144196/Accessed on 24 May 2013
- World Health Organization (2011) Rapid Implementation of the Xpert MTB/ RIF diagnostic test Technical and Operational 'How – to'; Practical consideration. Available: http://whqlibdoc.who.int/publications/2011/ 9789241501569_eng.pdf.
- Boehme CC, Nabeta P, Hillemann D, Nicol MP, Shenai S, et al. (2010) Rapid Molecular Detection of Tuberculosis and Rifampin Resistance. N Engl J Med 363: 1005–1015. Available: http://www.nejm.org/doi/pdf/10.1056/ NEJMoa0907847.
- Boehme CC, Nicol MP, Nabeta P, Michael JS, Gotuzzo E, et al. (2011) Feasibility, diagnostic accuracy, and eff ectiveness of decentralised use of the Xpert MTB/RIF test for diagnosis of tuberculosis and multidrug resistance: a multicentre implementation study. Lancet 377: 1495–1505. doi:10.1016/S0140-6736(11)60438-8.
- 7. Cepheid (2009) Xpert MTB/RIF Two-hour detection of MTB and resistance to rifampicin.
- Steingart KR, Sohn H, Schiller I, Kloda LA, Boehme CC, Pai M DN (2013) Xpert [®] MTB/RIF assay for pulmonary tuberculosis and rifampicin resistance in adults (Review). Chochrane Database Syst Rev. Available: http:// onlinelibrary.wiley.com/doi/10.1002/14651858.CD009593.pub2/pdf.
- National Health Laboratory Service South Africa (2013) GeneXpert MTB/RIF Progress Report February 2013.
- Tukvadze N, Kempker RR, Kalandadze I, Kurbatova E, Leonard MK, et al. (2012) Use of a Molecular Diagnostic Test in AFB Smear Positive Tuberculosis Suspects Greatly Reduces Time to Detection of Multidrug Resistant Tuberculosis. PLoS One 7: e31563. doi:10.1371/journal.pone.0031563.

this device in such settings would help in decision making at national level.

Author Contributions

Conceived and designed the experiments: NR PD KSS AS RSG B. Vadera MP RT RR UA MG B. Vollepore CB CNP. Performed the experiments: NR B. Vadera SK AB. Analyzed the data: NR B. Vadera SK AB AS KSS CG. Contributed reagents/materials/analysis tools: NR AS KSS RSG. Wrote the paper: NR B. Vadera SK AS KSS CNP CB.

- Albert H, Bwanga F, Mukkada S, Nyesiga B, Ademun JP, et al. (2010) Rapid screening of MDR-TB using molecular Line Probe Assay is feasible in Uganda. BMC Infect Dis 10: 41. doi:10.1186/1471-2334-10-41.
- Barnard M, Albert H, Coetzee G, O'Brien R, Bosman ME (2008) Rapid molecular screening for multidrug-resistant tuberculosis in a high-volume public health laboratory in South Africa. Am J Respir Crit Care Med 177: 787–792. doi:10.1164/rccm.200709-1436OC.
- World Health Organisation-Expert Group Report (2008) Molecular Line Probe Assays For Rapid Screening Of Patients At Risk Of Multi-Drug Resistant Tuberculosis (MDR-TB)
- Nikolayevsky V, et al. (2009) Performance of the Genotype [®] MTBDRPlus assay in the diagnosis of tuberculosis and drug resistance in Samara, Russian Federation. BMC Clin Pathol 9: 1–9. doi:10.1186/1472-6890-9-2.
- World Health Organization (2007) Use of Liquid TB Culture and Drug Susceptibility Testing (DST) in Low and Medium Income Settings Summary report of the Expert Group Meeting on the use of liquid culture media.
- Central TB Division Ministry of Health and Family Welfare (2009) Training Manual for Mycobacterium tuberculosis Culture & Drug susceptibility testing. New Delhi, India
- World Health Organization (2011) Automated Real-time Nucleic Acid Amplification Technology for Rapid and Simultaneous Detection of Tuberculosis and Rifampicin Resistance: Xpert MTB/RIF System. Geneva, Switzerland.
- World Health Organization- The STOP TB Department (2012) Update -Implementation and roll-out of Xpert MTB/RIF May 2012. Available: http:// www.stoptb.org/wg/gli/assets/documents/Xpert%20MTB-RIF%20UPDATE %20May%202012.pdf
- Chemhuru M, Duka M, Bernardin Nanan-n'zeth KJ, Simons S, Van Den Broucke S, et al. (2013) Implementation of Xpert MTB/RIF Assay in Buhera District, Zimbabwe: Lessons learned Available: http://www.msf.org.za/sites/ default/files/publication/documents/GeneXpert_report_Lessons_learned_ with_paralel_testing.pdf. Accessed 24 May 2013

- Cepheid (2013) Improving your experience with Xpert MTB/RIF," Cepheid HDBC, 2012. Available: http://www.ghdonline.org/uploads/Improving_your_ experience_of_Xpert_MTB_RIF.pdf. Accessed 24 May 2013
- André E, Chirambiza JP, Nyota R, Kalumuna D, Creswell J, et al. (2013) Lessons learned from early implementation of GeneXpert MTB/RIF technology in a remote area of the Democratic Republic of Congo in 19th Conference of the Union Africa Region Kigali